


Sampling Port Detail on Forcemain

Note: Sample port to be placed as close to tank as possible after all treatment.

O₂Si
UV Sterilizer

Sample Port Schematic

not to scale



Obsidian Onsite Services, inc.

P.O. Box 100
Tappahannock, VA 22560
(804) 347-7176